



This report provided free of charge by:

Lake Motor Group LLC1036 Reder Rd
Griffith, IN 46319
219-419-7699★ **4.5 / 5.0**
38 Verified Reviews**Report**

US \$44.99

2017 Ford Explorer XLT

139,955 mi | VIN: 1FM5K7D89HGC13374

4 Door Wagon/Sport Utility | 3.5L V6 F DOHC 24V | Gasoline | Front wheel drive



NO ACCIDENTS REPORTED

 No Accidents or Damage Reported to
CARFAX **23 Service History Records**

At Least 1 Open Recall

1 CARFAX 1-Owner Vehicle

Personal Vehicle

Last Owned in California

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/11/26 at 6:51:53 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

**Recent Service Highlights**

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	04/21/2026
Tires	Tires rotated	04/21/2026
 This car has been recently serviced. That's a good thing!		

**Additional History**

Not all accidents / issues are reported to CARFAX

Owner 1**Total Loss**

No total loss reported to CARFAX.

No Issues Reported

Structural Damage


No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	✓ No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	👤 Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	👤 Owner 1
Year purchased	2017
Type of owner	Personal
Estimated length of ownership	9 yrs. 3 mo.
Owned in the following states/provinces	California
Estimated miles driven per year	15,326/yr
Last reported odometer reading	139,955

CARFAX Detailed History			
👤 Owner 1 Purchased: 2017		Personal Vehicle 15,326 mi/yr	
Date	Mileage	Source	Comments
02/06/2017		Ford Motor Company	Vehicle manufactured and shipped to original dealer Original Window Sticker 
02/27/2017	37	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ❤️ 12,288 Customer Favorites	Vehicle sold - - -

03/06/2017		California Motor Vehicle Dept. Garden Grove, CA		Title issued or updated First owner reported - Titled or registered as personal vehicle - Loan or lien reported
07/20/2017	7,123	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked - Tire condition and pressure checked - -
12/16/2017	15,123	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced - Maintenance inspection completed Battery/charging system checked Brakes checked - Tire condition and pressure checked - Vehicle washed/detailed -
11/08/2018	30,168	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced - Maintenance inspection completed Battery/charging system checked Brakes checked - Tire condition and pressure checked - Vehicle washed/detailed -
03/16/2019	35,895	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked - Tire condition and pressure checked - -
04/06/2019	36,747	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Air filter replaced Antifreeze/coolant flushed/changed Battery/charging system checked Brakes checked - Tire condition and pressure checked
09/20/2019	45,169	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked - Tire condition and pressure checked - -
04/17/2020	52,961	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Alignment checked Battery/charging system checked Brakes checked - Four wheel alignment performed - Tire condition and pressure checked
11/14/2020	60,282	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced Maintenance inspection completed Tire condition and pressure checked - - -
05/14/2021	66,930	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked Brakes checked Oil and filter changed - Tire condition and pressure checked Tires rotated

08/19/2021		Ford Motor Company		Manufacturer Customer Satisfaction issued Program #21N01 HIGH SPEED COOLING FAN MOTOR RELAY Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
09/24/2021	72,626	BP Ford of Long Beach Long Beach, CA 562-420-3333 bpfordoflongbeach.com ★ 4.2 / 5.0 39 Verified Reviews ♥ 2 Customer Favorites		Vehicle serviced Oil and filter changed - -
02/19/2022	77,015	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced 45,000 mile service performed Tire condition and pressure checked - - -
07/27/2022	82,122	Villa Ford Of Orange Orange, CA 714-637-8222 davidwilsonvillaford.com ★ 4.5 / 5.0 730 Verified Reviews ♥ 12,288 Customer Favorites		Vehicle serviced Maintenance inspection completed Battery/charging system checked Brakes checked Oil and filter changed Tire condition and pressure checked Tires rotated
08/12/2022		Ford Motor Company		Manufacturer Safety recall issued NHTSA #19V651 Recall #19S29 SEAT FRAME BURRED EDGE Status: Remedy Available Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information Learn more about this recall
Description: ON YOUR VEHICLE, THE INBOARD POWER SEAT TRACK MAY HAVE A SHARP BURR DUE TO AN IMPROPERLY FINISHED EDGE. YOU COULD INJURE YOUR HAND IF YOU REACH BETWEEN THE FRONT SEAT AND CENTER CONSOLE, SUCH AS TO RETRIEVE A FALLEN OBJECT. Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSTALL FLOCKED TAPE OVER SEAT TRACK EDGE FREE OF CHARGE (PARTS AND LABOR).				
08/16/2022		California Motor Vehicle Dept.		Title issued or updated Loan or lien released
09/26/2022	84,670	Big Brand Tire Fullerton, CA 714-525-2306 bigbrandtire.com ★ 4.6 / 5.0 31 Verified Reviews ♥ 17 Customer Favorites		Vehicle serviced Tire(s) balanced -
11/04/2022		Ford Motor Company		Manufacturer Customer Satisfaction Program issued Program #21R01 REAR TOE LINK REPLACEMENT Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
01/06/2023	88,640	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced Oil and filter changed -

05/12/2023	94,120	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced - Oil and filter changed - -
10/09/2023	100,184	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Rear brakes replaced - Spark plug(s) replaced - Tires rotated
01/23/2024		Ford Motor Company		Manufacturer Safety recall issued NHTSA #24V031 Recall #24S02 EXTERIOR A-PILLAR APPLIQUE MOLDING INSPECTION Status: Remedy Available Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information  Learn more about this recall
Description: IN SOME OF THE AFFECTED VEHICLES, IT MAY BE POSSIBLE THAT SOME OF THE EXTERIOR A-PILLAR APPLIQUE TRIM CLIP ATTACHMENTS ARE NOT PROPERLY ENGAGED DUE TO IMPROPER ASSEMBLY OR REPAIR. IF THIS OCCURS, THE A-PILLAR APPLIQUE TRIM, WHICH BORDERS THE RIGHT AND LEFT SIDE OF THE WINDSHIELD, MAY BE LOOSE, MISSING OR BECOME DETACHED. AN EXTERIOR A-PILLAR TRIM PART THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH. Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPAIR ANY LOOSE OR MISSING EXTERIOR A-PILLAR TRIM MOLDINGS FREE OF CHARGE PARTS AND LABOR. A TEMPORARY REPAIR MAY ALSO BE COMPLETED AS NEEDED.				
03/02/2024	106,256	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
06/15/2024	111,851	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Front brakes replaced - Oil and filter changed - Tires rotated
10/26/2024	117,989	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced Maintenance inspection completed Oil and filter changed - Tires rotated - -
02/26/2025	123,426	California Inspection Station		Passed emissions inspection
02/27/2025		Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/ ★ 4.9 / 5.0 70 Verified Reviews ♥ 35 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated

05/27/2025	Ford Motor Company	Manufacturer Safety recall issued NHTSA #25V347 Recall #25S53 EXTERIOR B-PILLAR APPLIQUE MOLDING INSPECTION Status: Remedy Not Yet Available Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information  Learn more about this recall	
Description: ON YOUR VEHICLE, THE DRIVER AND FRONT PASSENGER DOOR B-PILLAR TRIM APPLIQUES MAY BECOME PARTIALLY OR FULLY DETACHED. YOU MAY VISUALLY NOTICE THE B-PILLAR TRIM APPLIQUES SEPARATING FROM THE TOP OF THE FRONT DOORS WHEN ENTERING EXITING THE VEHICLE AND OR HEAR WIND NOISE AND RATTLING NOISE AS YOU DRIVE. THIS MAY RESULT IN THE B-PILLAR TRIM APPLIQUES DETACHING WHILE DRIVING. A B-PILLAR TRIM APPLIQUE THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER VEHICLES, INCREASING THE RISK OF A CRASH. Remedy: FORD MOTOR COMPANY IS WORKING TO PROVIDE PARTS FOR THIS REPAIR. WHEN THE REMEDY BECOMES AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE.			
08/02/2025	128,926	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/  4.9 / 5.0 70 Verified Reviews  35 Customer Favorites	 Vehicle serviced Maintenance inspection completed Oil and filter changed Tires rotated
01/10/2026	134,850	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/  4.9 / 5.0 70 Verified Reviews  35 Customer Favorites	 Vehicle serviced Maintenance inspection completed Oil and filter changed Spark plug(s) replaced Stabilizer bar links replaced Sway bar link(s) replaced Tires rotated
04/02/2026		Ford Motor Company	Manufacturer Customer Satisfaction issued Program #25N17 REAR VIEW CAMERA REPLACEMENT IF REQUIRED AFTER DEALER EVALUATION Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information
04/21/2026	139,955	Cooks Tire & Tune Fullerton, CA 714-870-0100 cookstireandtune.com/  4.9 / 5.0 70 Verified Reviews  35 Customer Favorites	 Vehicle serviced Maintenance inspection completed Oil and filter changed Tires rotated
06/17/2026		Online Listing	Vehicle offered for sale
07/02/2026		Ford Motor Company	Manufacturer Emission recall issued Recall #25E10 POWERTRAIN CONTROL MODULE PCM REPROGRAMMING Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford or Lincoln Mercury Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Service Campaign

Automobile manufacturers issue a service campaign to address product technical issues that may not be related to safety or emissions standards. These issues are typically customer satisfaction initiatives.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:facebook.com/CARFAX[@CARFAXinc](https://twitter.com/CARFAXinc)[About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
7/11/26 6:51:53 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2017 FORD EXPLORER vehicle (VIN: 1FM5K7D89HGC13374), which is based on information supplied to CARFAX and available as of 7/11/26 at 7:51 PM (EDT).

Customer Signature

Date

Dealer Signature

Date